# **UNCLASSIFIED**

UNCLASSIFIED
AD NUMBER: AD0803127
LIMITATION CHANGES
TO:
Approved for public release; distribution is unlimited.
FROM:
Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; 31 DEC 1960. Other requests shall be referred to Army Natick Labs., MA
AUTHORITY
St A USANL ltr 7 Oct 1971

803127




RDT&E PROJECT NO 1M643303D547
USATECOM PROJECT NO 8-6-6010-01

SERVICE TEST OF BOOT, COMBAT,
TROPICAL, DMS WITH SPIKE RESISTANT SOLE SHIELD

FINAL REPORT

by MSG Columbus Sims, Jr.

August 1966



# UNITED STATES ARMY TROPIC TEST CENTER

This document may be further distributed by any holder only with specific prior approval of US Army Natick Laboratories

# DISPOSITION INSTRUCTIONS

Destroy this report when no longer needed. Do not return it to the originator.

# DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

# RDT&E PROJECT NO 1M643303D547

USATECOM PROJECT NO 8-6-6010-01

SERVICE TEST OF BOOT, COMBAT, TROPICAL, DMS WITH SPIKE RESISTANT SOLE SHIELD

FINAL REPORT

by MSG Columbus Sims, Jr.

August 1966

APPROVED:

PEDRO R. FLORCRUZ Colonel, Infantry Commanding

This document may be further distributed by any holder only with specific prior approval of US Army Natick Laboratories

UNITED STATES ARMY TROPIC TEST CENTER Fort Clayton, Canal Zone

#### ABSTRACT

The Boot, Combat, Tropical, Direct Molded Sole with Spike Resistant Sole Shield, was service tested by the US Army Tropic Test Center in the Canal Zone during the period 21 February thru 21 June 1966. The test sample consisted of 85 pairs of boots. The boots were worn by personnel from airborne, mechanized, and regular infantry battalions, special forces units, and by field cadre at the US Army School of the Americas and the US Air Force Tropic Survival School. Use included local unit training and field exercises. (Test of protection against spikes was conducted by the US Army General Equipment Test Activity at Fort Lee, Virginia, and was not a part of the tropic test.) The test boot was found to be functionally suitable for field and garrison wear in the warm wet climate. The bonding of the rubber sole and heel and the ventilation and drainage eyelets are satisfactory to withstand at least 121 days use under rugged field conditions. Cracks developed in the center cleat-sole junction of the rubber sole on five pairs of boots during normal use. Seven failures were noted in the bonding of the rubber heel to the outsole. It was recommended that the Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, be considered suitable for Army use when shortcomings are corrected.

#### FOREWORD

This document reports the results of the service test of the Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, conducted by the US Army Tropic Test Center under tropic environmental conditions. Testing was directed by US Army Test and Evaluation Command under USATECOM Project No 8-6-6010-01.

US Army Tropic Test Center was responsible for preparing the test plan, test execution and preparing the test report.

The author gratefully acknowledges the personnel support provided by the Jungle Operations Committee, US Army School of the Americas; 8th Special Forces Group (Airborne); 3d Battalion (Airborne), 508th Infantry; 4th Battalion, 10th Infantry; 4th Battalion (Mechanized), 20th Infantry; and US Air Force Tropic Survival School (Cadre).

# TABLE OF CONTENTS

	PAGE
ABSTRACT	ii
FOREWORD	iii
SECTION 1. INTRODUCTION	
1.1 BACKGROUND	1 2 2 3
1.5 CONCLUSIONS	4
SECTION 2. DETAILS OF TEST	
2.1 INTRODUCTION	5 7 10
SECTION 3. APPENDICES	
TEST DATA	. 14 . 24 . 25
MAINTENANCE EVALUATION	. 26 . 27 . 31 . 32

# SECTION 1. INTRODUCTION

# 1.1 BACKGROUND

Hostile troops include in their guerrilla tactics the use of sharp spikes of metal or bamboo, strategically placed on the ground or under water in such a manner that they can penetrate the outsoles of conventional footwear and cause numerous foot injuries.

The Office of the Quartermaster General directed that efforts be made to counteract such tactics. Research in response to this directive, begun in October 1961, resulted in the development of a protective spike resistant insole (insert type) which was tested by the US Army Airborne, Electronics and Special Warfare Board under Project No. 1262, type classified Limited Production and procured in accordance with Limited Production Purchase Description 39-63.

US Army Natick Laboratories subsequently developed a Boot, Combat, Tropical, Direct Molded Sole with Sole Shield, Spike Resistant. This boot incorporated as an integral part a sole shield consisting of a series of overlapping stainless steel strips. Single strips of stainless steel protected the toe area (two inches) and the heel to shank area (four inches), with overlapping 3/4-inch strips protecting the rest of the plantar surface of the foot. Testing of this boot was accomplished in 1961 by the US Army General Equipment Test Activity and the US Army Infantry Board. These tests revealed shifting of the overlapping strips to the extent that the sole shield was rendered ineffective as a protective device.

In June 1964, US Army Combat Developments Command reported results of a detailed review of the need for protection of the plantar surface of the foot against spike devices. Fundamental among these results was a determination that for certain special warfare personnel operating in areas of actual or potential hazards a limited requirement exists for protection. Spike injuries in general and plantar-surface injuries in particular constitute a relatively small percentage of total battle casualties in the Republic of Vietnam. US Army Combat Developments Command stated that 60% of wounds from spike devices in the Republic of Vietnam have been incurred above the foot. US Army Combat Developments Command recommended that foot protection be provided on an "as required" basis, using an improved slip insole.

On 2 November 1964, US Army Test and Evaluation Command directed the US Army Tropic Test Center to conduct a service test

of the Spike Resistant Insole. As a result of actions to correct deficiencies reported in this test and others, a new boot was designed for test.

On 26 November 1965, US Army Tropic Test Center was directed to conduct a service test of the new Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield. The test was conducted from 21 February to 21 June 1966. Concurrent with this test, the US Army General Equipment Test Activity conducted an engineering test.

#### 1.2 DESCRIPTION OF MATERIEL

The test item is the Boot, Combat, Tropical, DMS with a solid steel plate built into the midsole. This plate is made of .011 inch gauge stainless steel. The boot has a cleated sole and heel vulcanized and molded directly to the leather upper. The outsole is made from two "biscuits" of uncured rubber, one "biscuit" forming the entire tread surface of the outsole and one "biscuit" forming the tread surface of the heel. Vulcanization under pressure cures or "knits" the two biscuits into a one-piece sole and heel while simultaneously bonding sole and heel directly to the upper. The boot upper is composed of leather vamp, leather counter, leather eyelet stay and nylon/cotton top facing, quarters and gusset. The boot has a cloth vamp lining with a polystyrene box toe between the lining and the leather vamp. The gusset is attached all the way to the top of the boot to prevent entry of leeches, etc., when the wearer is wading through swampy areas. The quarters and gusset are treated with a copper-8-quinolinolate to impart mildew resistance to the cotton. Brass eyelets are positioned in the rear of the inside ball area of the leather vamp to provide ventilation and to allow water to drain from the boot (see Figure 1, Appendix V).

The term "bonding failure" is used to denote failure of the rubber material to adhere to the leather material with resultant separation of the outsole from boot upper.

The term "knitting failure" is used to denote failure of the two biscuits of identical rubber compound to cohere with resultant separation of heel from sole material or degradation of heel material.

#### 1.3 OBJECTIVE

To determine the suitability of the test item for use by US Army personnel in the humid tropics with particular attention to

comfort, mobility and durability. (Test objective does not include determination of the boot's resistance to spike penetration.)

#### 1.4 SUMMARY OF RESULTS

- a. The test boot met requirements for garrison and field use under warm-wet climatic conditions with respect to comfort, foot and ankle support, ease of donning and doffing, adequacy of closure, and drying characteristics.
- b. The test boot was very acceptable to the soldier in the tropics and was preferred for jungle wear over the standard, all-leather, combat boot and the old jungle boot with buckle top.
- c. The boot afforded the wearer adequate protection from underbrush, insects and other objects normally encountered when walking through the jungle. There are no leeches in the Canal Zone. No penetration of the boot sole by sharp wooden or metal spikes occurred during normal use.
- d. No chafing or blistering of the foot was caused by the spike resistant sole shield.
- e. The test boot was compatible with the field uniform and presented a satisfactory appearance; however, the top of the boot is too short to allow blousing of the trousers inside the top of the boot.
- f. The cloth quarters became stained from jungle wear and shoe polish. No adverse functional effects were observed as a result. Ease of maintenance would be improved if the cloth were black.
- g. Satisfactory traction was provided by the cleated sole, but traction was diminished somewhat by mud and small rocks sticking between the sole cleats.
- h. No failures were observed in the bonding of the rubber sole to the leather upper. However, failures in the bonding of the rubber heel to the outsole were observed in seven pairs of the boots. This is a shortcoming.
- i. Two ventilation and drainage eyelets became dislodged during the test period. This is a shortcoming.
- j. The boot was found to be sufficiently durable for at least 121 days of wear in a warm-wet environment.

- k. On one boot the top of the cloth gusset, beneath the edging tape, was torn from pulling on the gusset while donning the boot. This is a shortcoming.
- 1. On five pairs of boots, cracks developed in the rubber sole at the intersection of the middle cleats and front end of the steel shank. This is a shortcoming.
- m. The edge of the saran insole frayed after two to three months of use, causing some discomfort to the wearer. This is a shortcoming.

# 1.5 CONCLUSIONS

The Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, is suitable for Army use in warm-wet climatic conditions for periods of wear of 121 days. The boots will probably remain serviceable for periods of wear much longer than 121 days, but the expected life of the boots was not determined by this cest.

#### 1.6 RECOMMENDATIONS

- a. That the Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, be considered suitable for Army use when the short-comings listed in Appendix III are corrected.
  - b. That the cloth quarters of the boot be colored black.

#### SECTION 2. DETAILS OF TEST

#### 2.1 INTRODUCTION

# 2.1.1 Test Sample

Ninety pairs of test boots (Figure 1, Appendix V), less five pairs withdrawn for orientation use by Tropic Test Center, were issued to selected groups of test personnel in US Army units on duty in the Canal Zone.

# 2.1.2 Test Procedure

Test participants subjected the test item to maximum wear conditions by use in normal operations, both in the jungle and in the tropical savanna areas existing in the Canal Zone and Rio Hato, Republic of Panama, respectively. The following distribution of test boots was made.

Unit	Number of Pairs Assigned
UIII	
US Air Force Tropic Survival School (Cadre)	11
Jungle Operations Committee, US Army School of the Americas (Cadre)	16
8th Special Forces Group (Airborne)	9
3d Battalion (Airborne), 508th Infantry	16
4th Battalion, 10th Infantry	16
4th Battalion (Mechanized), 20th Infantry	17

Each supporting unit designated a unit project officer and a test recorder to assist in control and supervision of the test in his respective unit.

The wear test extended over a period of approximately four months.

Five pairs of boots were withdrawn after each 30 days of wear and examined by the engineering test agency (US Army General Equipment Test Activity).

# 2.1.3 Test Data

The service test utilized the results obtained from normal wear by test participants in field and garrison operations in a natural, humid, tropical environment to determine the suitability and durability of the boots. Test data were gathered from interviews, direct observation and subjective opinions solicited from test participants on questionnaires. Questionnaires were administered upon withdrawal of boots from the test, after two months of wear and at the end of the test period. Five of the original 85 pairs issued were withdrawn from the test for various reasons, such as nonavailability of test participants over the entire test period due to transfer to Vietnam and CONUS. The use of six test groups engaged in a variety of missions insured rigorous testing in a variety of different operations and conditions not possible with one group.

Visual inspection for any defects that might alter test results was made of all test boots prior to issue.

All boots were code-marked with Arabic numerals from 1 thru 90 for identification and future reference in case of failures.

Each test participant had five or more months expected retainability in his unit.

Each test participant was individually fitted with a pair of precoded test boots by a qualified fitter, using a calibrated foot-measuring device. Each test participant was issued a properly-fitted new pair of standard cushion-sole socks to be worn during the initial fitting.

The fitting of the test boots was considered correct based upon the opinions of the fitting technician and the test participant. The ease of fitting the test boot to participants and any evidence of improper sizing (labeled versus actual) were noted. Only test participants with correctly fitted boots were used in the test.

Ambient weather data, to include daily extremes of temperature, relative humidity and precipitation in the Canal Zone, were recorded during the test period on each side of the Isthmus (Charts 1 and 2, Appendix I).

Still pictures were used, when appropriate, to supplement other data obtained during the test.

# 2.1.4 Safety

Developer Safety Statement: Research, development and testing to date have demonstrated nothing to contraindicate wear or use of subject item by test personnel from a safety standpoint.

#### 2.1.5 Control Item

No control items were used in the conduct of this test; however, test participants were asked to relate their appraisal of the test boot to the type of combat boot which they ordinarily would be wearing.

# 2.2 SUBTEST NO 1 - SUITABILITY AND COMFORT

# 2.2.1 Objectives

- a. To determine whether the test boot was functionally suitable for use in a variety of occupational duties, both in the field and in garrison, under warm-wet climatic conditions.
- b. To determine the effects of the sole shield on the comfort of the individual.

# 2.2.2 Method

Test participants were instructed in the objective of the service test and were requested to wear the test boots continually while they were in the field participating in all activities associated with range firing, unit training, field exercises, parachute jumps and Army Training Tests and while in garrison performing regular duties. The test boot was not worn on an alternate basis with any other type combat boot except for health reasons, as directed by a medical officer, or in instances where the test boot had become thoroughly wet and was being allowed to dry.

The effect of the boot on the mobility of the wearer, when used to traverse terrain features, was determined to include stability and traction afforded the wearer and restrictions of the boot on movement.

At the conclusion of the first two-month wearing test period and at the conclusion of the test wear period, each test participant answered a questionnaire to provide subjective data and to express his opinion with respect to each of the following characteristics of the test boot. (Because of the close similarity in responses, only the test end questionnaires were used for the statistical data in Appendix 1.)

- a. Suitability of fit at beginning and end of the wearing test period.
- b. Comfort, with emphasis on chafing of the foot caused by the spike resistant sole shield.
  - c. Foot and ankle support.
- d. Protection afforded to the wearer from underbrush, insects and sharp objects.
  - e. Ease of donning and doffing.
  - f. Adequacy of closure.
  - g. Compatibility with field uniform.
  - h. Appearance.
- i. Traction provided by cleated sole and heel under various conditions and other characteristics which affect the mobility of the wearer.
  - j. Self-cleaning ability of sole and heel cleats.
  - k. Drying characteristics.
  - 1. Ability to drain water.
- m. Durability, with particular attention to adequacy of the bond and knit of the sole and heel.
  - n. Overall troop acceptability.

Each test participant was asked to state a preference for either the test boot or the standard combat boot for Army use in a warm-wet climate.

## 2.2.3 Results

No evidence of improper sizing (labeled versus actual) was noted when fitting the boots. The test participants' responses on

suitability of the boots covered in paragraph 2.2.2a-n are shown in Tables 1-8, Appendix I.

Test participants stated that the boots dried in from one and one-half to eight hours, with an average time of three hours, under field conditions after being completely wetted.

# 2.2.4 Analysis

The test boots are sized properly. Three test participants stated that they would have preferred a one or one-half size smaller than they were issued.

A small number of test participants stated that the boots expanded a little during wear and became loose on their feet. This observation is not considered unusual in the wear of footwear in the tropical environment where the boot is wet both by immersion and by perspiration daily. The looseness can be compensated in most cases by wearing heavier socks.

Two test participants stated that the overlap of the gusset causes lumpy areas which press on the ankle, causing a slight discomfort.

The test boots are comfortable for wear, and no significant chafing or blistering of the feet or other discomfort is caused by the solid steel plate built into the midsole.

The foot and ankle support provided by the test boot is adequate for normal field wear. The boots can be worn safely while performing parachute jumps even though not as much foot and ankle support is provided by the test boots as is provided by the standard, all-leather, combat boot.

The boot provided adequate protection against insects, underbrush and other objects normally encountered while moving through the jungle. Protection against leeches could not be determined due to the absence of leeches in the Canal Zone. Several test participants remarked that the canvas sides of the boots were penetrated by sharp spines, such as those on the Black Palm, or thorny bushes in the jungle. However, no serious injuries were sustained. No penetration of the sole was noted or reported during the test period.

The boots are easily donned and doffed, and the closure of the boot is adequate.

In its present form, the test boot is compatible with the field uniform; however, many of the test participants stated that a boot top one to two inches higher or trousers made one to two inches longer is more desirable because they could then blouse their trousers easier and present a more military appearance.

The appearance of the test boot is satisfactory; however, the green cloth quarters become stained after field use and it is difficult to keep shoe polish from streaking areas of the cloth immediately adjacent to the leather upper when applying black boot polish. A few test participants dyed the green upper with black leather dye to conform more with other personnel wearing standard, all-leather, combat boots in garrison. The dyeing of the cloth did not appear to have any adverse effects on the comfort of the boot. The leather surface can be easily polished with most brands of wax shoe polish.

The traction provided by the cleats on the test boot in normal field use in the jungle and other terrain found in the tropical environment is satisfactory, but traction is diminished somewhat by silty mud and wet clay clinging between the cleats. Mud and clay cling to the soles and cleats when wet, but fall off when dry. Small rocks lodge between the cleats and must be extracted by pushing with a stick or small tool (Pigure 2, Appendix V). The present cleat pattern and spacing at the ground contact surface is considered satisfactory for traction and weight distribution, but the self-cleaning characteristic of the cleats should be improved.

The drying characteristics of the boot are satisfactory, both while being worn and when off the feet. Water will drain from the drainage and ventilation eyelets unless they are plugged with mud or other foreign matter. The drainage vents usually can be easily unplugged by flushing with water. Wetting and drying did not adversely affect the leather of the boots, but the cloth upper showed signs of facing.

The test boot is very acceptable to US Army and Air Force personnel and much preferred for use in the tropics over the standard all-leather boot or the old jungle boot with buckle top.

#### 2.3 SUBTEST NO 2 - DURABILITY

#### 2.3.1 Objective

To determine the overall durability of the test boot when worn for extended periods under warm-wet climatic conditions with

emphasis on detection of bonding and knitting failures of the outsole and separation of the modified eyelet from the test boot.

# 2.3.2 Method

Throughout the wearing test period, supervisory test personnel monitored the performance of the test boots, paying particular attention to any failure of the bond of the sole and the leather upper, separation of the heel from the sole, separation of eyelets from the boot, uneven wear of the heel and sole, seam separation, shifting, fracturing or any other action of the sole shield to determine if there was any evidence of lack of durability.

The test participants were requested to report immediately to the unit project officer any sign of failure of the bond of the sole to the leather upper, any separation of the heel from the sole or any other major failure of the test boot.

#### 2.3.3 Results

No failures were observed in the bond of the rubber sole to the leather upper; however, seven failures were observed in the bonding of the heel to the leather upper (Figure 3, Appendix V). This is a shortcoming.

Ventilation and drainage eyelets separated from two different boots during the test (Figure 4, Appendix V).

The amount of surface worn off the cleats during the test period was very minor. In general, more wear occurred on the heel and toes than in other parts of the sole. The amount and location of wear points varied with the individual.

The top of the gusset on one pair of boots was ripped. In this case, the cloth failed at the edging tape when the gusset was pulled during donning action, and a two-inch tear resulted (Figure 5, Appendix V).

No lacing eyelets pulled out of the boots during the test.

At the end of the test period, five of the eighty pairs of test boots showed cracking of the sole (Figure 6, Appendix V). The cracks occurred only at the cleat-sole junction of the large center cleat and front end of the shank. No cracks were observed in the heel area.

Approximately 30% of the saran insoles showed signs of abrasive wear at areas in contact with the ball and heel of the boot. Very little fraying was noted along the bonded edge of the insole.

# 2.3.4 Analysis

Seventy-five of the 80 pairs of boots were serviceable at the end of 121 test days (101 average wear period).

The sole cracks noted in paragraph 2.3.3 appeared to be caused by the normal flexing of the sole during wear of the boot. The cracks behind the main cleat are apparently due to the high stress at this point caused by the end of the steel plate (shank) in the last. The exact time when the boot soles began cracking is undetermined; however, no difficulties were encountered by the test participants while wearing the boots with these cracks. The failure appeared to be a failure of the rubber itself and not a failure in the knit or bond of the molded sole. This failure in the boot sole is considered a shortcoming.

The separation of the bonding of the heel to the leather upper seems to be caused by frequent wetting and drying. It appears correctable by using an improved adhesive and forming the entire tread surface around the heel. This failure in the boot heel bonding is considered a shortcoming.

The fraying of the saran insole did not decrease its usability, but the frayed ends of the fibers do cause some discomfort. The tendency of the edge of the insole to fray is considered a shortcoming and should be eliminated, if possible.

# SECTION 3, APPENDICES

- I. TEST DATA
- II. FINDINGS
- III. DEFICIENCIES AND SHORTCOMINGS
- IV. MAINTENANCE TVALUATION
- V. PHOTOGRAPHS
- VI. REFERENCES
- VII. DISTRIBUTION LIST

# APPENDIX I. TEST DATA

TABLE 1

NUMBER AND SIZE OF BOOT TEST SAMPLE

WIDTHS				Sizes			TOTAL T
MIDIUS	7	8	9	10	11	12	TOTAL
N	-	-	8	8	4	2	22
R	2	5	22	13	3	2	47
W	3	8	7	3	-	-	21
TOTALS	5	13	37	22	7	4	90

TABLE 2

WEAR OF TEST BOOTS

				Number o	Number of Days of Wear Per	Wear Per
	Number	Number of Pairs of Boots	Boots		Individual	
	Original	Withdrawn	Firtshed			Weighted
Unit	Issue	from Test	Teart	Maximum	Minimum	Average
3d Bn (Abn), 508th Inf	16	7	14	120	09	85
4th Bn (Mech), 20th Inf	17	0	17	120	15	113
4th Bn, 10th Inf	16	ო	13	120	02	114
8th Special Forces Gp (Abn)	6	0	6	100	07	75
AF Tropic Survival School	11	0	p-4 p-4	121	20	102
Jungle Operations Committee, USA School of the Americas	16	0	16	121	90	106
TOTAL	85	5	80	OVERALL	OVERALL WEIGHTED AVG: 101	VG: 101

TABLE 3

TEST PARTICIPANTS' OPINION OF FIT
OF TEST BOOT AT BEGINNING AND END OF TEST

(80 Test Participants)

Andrew Control of the	At Beg:	_	At En	
Unit	Good	Bad	Good	Bad
3d Bm (Abm), 508th Inf	14	0	14	0
4th Bn (Mech), 20th Inf	17	0	17	0
4th Bn, 10th Inf	13	0	13	0
8th Special Forces Gp (Abn)	8	1	9	0
AF Tropic Survival School	11	0	11	0
Jungle Operations Committee, USA School of the Americas	14	2	16	0
TOTAL	77	3	80	0
PERCENTAGE	96.25	3.75	100	0

TABLE 4

TEST PARTICIPANTS' ANSWERS TO QUESTIONS ON COMPORT, CHAFING AND FOOT AND ANKLE SUPPORT

(80 Test Participants)

					Adequ	ate Foo	Adequate Foot and Ankle	cle
						Support	rt	
			Chafing or	ig or	Regular	ar	Parachute	ıte
	Comfortable	table	Blistering	ring	Duty		Jumps	50
Unit	Yes	No	Yes	æ	Yes	No	Yes	્ટ
3d Bn (Abn), 508th Inf	13	-	0	14	12	2	12	2
4th Bn (Mech), 20th Inf	16		0	17	17	0	NA	
4th Bn, 10th Inf	12	<b>,-4</b>	-	12	13	0	NA .	
8th Special Forces Group (Abn)	7	7	0	6	6	0	6	)
AF Tropic Survival School	11	0	၁	p=1 p=4	11	0	NA	
Jungle Operations Committee, USA School of the Americas	13	<b>m</b>	4	12	16	D	NA	
TOTAL	72	8	\$	75	78	2	21	2
PERCENTAGE	8	10	6.25	93.75	97.5	2.5	91.3	8.7

TABLE 5

TEST PARTICIPANTS' ANSWERS TO QUESTIONS ON SENSE OF COOLNESS AND VENTILATION, ADEQUATE PROTECTION AND EASE OF DONNING AND DOFFING

(80 Test Participants)

	Sense	9	Adequate	ate				
	Coolness	ess	Protection	ction				
	and		from	E		Ease of	t o	
	Ventilation	ation	Underbrush	brush	Donning	ing	Doffing	ing
Unit	Yes	No	Yes	£	Yes	No No	Yes	No
3d Bn (Abn), 508th Inf	13	H	13	-	14	0	14	0
4th Bn (Mech), 20th Inf	16	H	13	7	17	0	17	0
4th Bn, 10th Inf	13	0	13	0	13	0	13	,
8th Special Forces Group (Abn)	œ	<b>,</b>	9	ю	6	0	6	0
AF Tropic Survival School	11	0	7	0	-	0	# 4 p=4	0
Jungle Operations Committee, USA School of the Americas	15		15	-	16	0	16	0
TOTAL	76	7	7.1	6	80	0	80	0
PERCENTAGE	95	2	88.75	11.25	100	0	100	ပ

TABLE 6

TEST PARTICIPANTS' ANSWERS TO QUESTIONS ON CLOSURE, BLOUSING OF TROUSERS, APPEARANCE AND TRACTION

(80 Test Participants)

Unit         Adequate         Blousing         Desirable           Closure         of Trousers         Appearance           3d Bn (Abn), 508th Inf         13         1         9         5         14         0           4th Bn (Mech), 20th Inf         15         2         8         9         15         2           4th Bn, 10th Inf         13         0         10         3         13         0           8th Special Forces Group (Abn)         9         0         4         5         9         0           AF Tropic Survival School         11         0         9         2         11         0           Jungle Operations Committee,         16         0         14         5         9         0           USA School of the Americas         15         3         54         26         78         2           TOTAL         77         3         57         57         2         5           PERCENTAGE         96.25         3.75         67.5         32.5         97.5         2.5				Easy	<b>A</b>				
Closure         of Trousers         Appearan           1 (Abn), 508th Inf         13         1         9         5         14           8n (Mech), 20th Inf         15         2         8         9         15           8n, 10th Inf         13         0         10         3         13           Special Forces Group (Abn)         9         0         4         5         9           copic Survival School         11         0         9         2         11           le Operations Committee,         16         0         14         5         9           School of the Americas         77         3         54         26         78           L         77         3         54         26         78           SurAGE         96.25         3.75         67.5         32.5         97.5		Adequ	late	Blous	fug	Desira	abie	Adequate	ate
No       Yes       No       Yes       No       Yes         1 (Abn), 508th Inf       13       1       9       5       14         Bn (Mech), 20th Inf       15       2       8       9       15         Bn, 10th Inf       13       0       10       3       13         Special Forces Group (Abn)       9       0       4       5       9         ropic Survival School       11       0       9       2       11         le Operations Committee,       16       0       12       2       16         School of the Americas       77       3       54       26       78         L       77       3       55       67.5       32.5       97.5		Close	ıre	of Tro	users	Appear	rance	Traction	ton
13     1     9     5     14       15     2     8     9     15       13     0     10     3     13       9     0     4     5     9       11     0     9     2     11       16     0     14     2     16       77     3     54     26     78       96.25     3.75     67.5     32.5     97.5	Unit	Yes	£	Yes	2	Yes	No	Yes	S.
15     2     8     9     15       13     0     10     3     13       9     0     4     5     9       11     0     9     2     11       16     0     1.4     2     11       77     3     54     26     78       96.25     3.75     67.5     32.5     97.5	3d Bn (Abn), 508th Inf	13	-	6	٠	14	0	13	<i>-</i>
13     0     10     3     13       9     0     4     5     9       11     0     9     2     11       16     0     14     2     11       77     3     54     26     78       96.25     3.75     67.5     32.5     97.5		15	2	ω	σ	15	2	16	<i>,</i> —1
9     0     4     5     9       11     0     9     2     11       16     0     14     2     11       77     3     54     26     78       96.25     3.75     67.5     32.5     97.5	4th Bn, 10th Inf	13	0	10	М	13	0	13	0
11     0     9     2     11       16     0     14     2     16       77     3     54     26     78       96.25     3.75     67.5     32.5     97.5	8th Special Forces Group (Abn)	6	0	4	٧	6	0	6	0
16     0     14     2     16       77     3     54     26     78       96.25     3.75     67.5     32.5     97.5	AF Tropic Survival School	П	0	6	7	Π	0	<u></u>	0
77 3 54 26 78 NTAGE 96.25 3.75 67.5 32.5 97.5	Jungle Operations Committee, USA School of the Americas	16	0	**	2	16	0	11	8
96.25 3.75 67.5 32.5 97.5	TOTAL	77	3	54	26	78	2	73	7
	PERCENTAGE	96.25	3.75	67.5	32.5	97.5	2.5	91.25	8.75

TABLE 7

TEST PARTICIPANTS' ANSWERS TO QUESTIONS ON FLEXIBILITY, SELF-CLEANING ABILITY, ADVERSE EFFECTS OF REPETITIVE WETTING AND DRYING, AND ABILITY TO DRAIN WATER

(80 Test Participants)


Clears   Effects   Effects   Self-   Of Wetfing   Drain Water   Self-   Of Wetfing   Drain Water   Self-   Of Wetfing   Drain Water   No   Yes   Yes						Adverse	18e		
Rechnity (Abm), 508th Inf         Flexibility (Cleaning Self- of Wetting Should be betting Abm)         Flexibility (Cleaning Abm)         Self- of Wetting Abm of Yes No				Cle	ts	Effe	cts		
No   Yes   No   Yes   No   Yes   No   Yes   No   Yes   No		,		Seli	.1.	of Wet	tting		
No         Yes         No         Yes         No         Yes         No           n (Abn), 508th Inf         14         C         10         4         0         14           Bn (Mech), 20th Inf         17         0         10         7         2         15           En, 10th Inf         13         0         8         5         1         12           Special Forces Group (Abn)         8         1         5         4         1         8           ropic Survival School         11         0         8         3         1         10           le Operations Committee,         16         0         4         12         2         14           School of the Americas         16         0         4         12         2         14           L         79         1         45         35         7         73           ENTAGE         98.75         1.25         56.25         43.75         91.25		Flexib	flity	Clear	1108	and Dr	cying	Drain	Water
14       C       10       4       0       14         17       0       10       7       2       15         p (Abn)       8       1       5       4       1       12         ol       11       0       8       3       1       8         ol       11       0       8       3       1       10         ttee,       16       0       4       12       2       14         1cas       1       45       35       7       73         98.75       1.25       56.25       43.75       8.75       91.25	Unit	Yes	£	Yes	S.	Yes	æ	Yes	No
p (Abn)     8     5     1     12       ol     11     5     4     1     8       ol     11     5     4     1     8       ttee,     16     0     4     12     2     14       tcas     1     45     35     7     73       98.75     1.25     56.25     43.75     8.75     91.25	3d Bn (Abn), 508th Inf	14	ပ	10	4	0	14	14	0
(Abn)         8         5         1         12           ee,         16         0         4         12         2         14           as         1         45         35         7         73           98.75         1.25         56.25         43.75         8.75         91.25	4th Bm (Mech), 20th Inf	17	0	01	7	7	15	17	O
(Abn)         8         1         5         4         1         8           11         0         8         3         1         10           ee,         16         0         4         12         2         14           as         7         4         12         2         14           79         1         45         35         7         73           98.75         1.25         56.25         43.75         8.75         91.25	4th Bn, 10th Inf	13	0	<b>∞</b>	5	H	12	13	0
ee, 16 0 4 12 2 14  as 79 1 45 35 7 73  98.75 1.25 56.25 43.75 8.75 91.25	8th Special Forces Group (Abn)	<b>∞</b>	-	2	7	<b>,</b> 1	œ	6	0
16         0         4         12         2         14           79         1         45         35         7         73           98.75         1.25         56.25         43.75         8.75         91.25	AF Tropic Survival School	11	0	80	e	-	10	7	0
79     1     45     35     7     73       NTAGE     98.75     1.25     56.25     43.75     8.75     91.25	Jungle Operations Committee, USA School of the Americas	16	0	4	12	2	14	16	O
98.75 1.25 56.25 43.75 8.75 91.25	TOTAL	79	П	45	35	7	73	80	0
	PERCENTAGE	98.75	1.25	56.25	43.75	8.75	91.25	100	0


TABLE 8

TEST PARTICIPANTS' RATING FOR ACCEPTABILITY FOR THE TEST BOOT AND PREFERENCE FOR TEST BOOT, STANDARD ALL-LEATHER COMBAT BOOT, OR JUNGLE BOOT W/BUCKLE TOP

(80 Test Participants)

		Rati	Rating of		Test Boot	ot				
	οŢG	)]6	oje sja		able:	2TOP			Preference B	For
Unit	Extremel Acceptab	Acceptat Very	Moderate Acceptate	Acceptεt Just	Slightly Unaccept	Nusccept Very	Extremel Unaccept	Test Boot	Standard All-Leather Combat Boot	Jungle Boot w/Buckle Top
4th Bn (Mech), 20th Inf	13	8	,	7	,		,	15	0	2
3d Bn (Abn), 508th Inf	ω	7	<del></del>	-	,	,	ı	12	0	2
8th Special Forces Gp (Abn)	7	7	ı	ı	i	1	ı	6	0	0
4th Bn, 10th Inf	9	7	1	ı	· · · · · · · · · · · · · · · · · · ·	ı	1	13	0	0
AF Tropic Survival School	6	7	ı	,	ı	,	ı	11	0	0
Jungle Operations Committee, USA School of the Americas	10	S	<b>,</b>	1	•	•	•	15	0	1
TOTAL	53	23	2	2	1	t	ı	52	0	5
PERCENTAGE	66.3	66.328.7	2.5	2.5	•	•	•	93.75	0	6.25





CLIMATIC DATA 21 FEB 66 THRU 21 JUNE 66
FORT SHERMAN C.Z. & VICINITY

# APPENDIX II, FINDINGS

Security and the second	Complied with	
The state of the s	Requirement	Remarks
<ol> <li>The boots shall produce no physical effects to the feet of the wearer attributable to the steel plate.</li> </ol>	Yes	See paragraph 2.2.4.
2. The boots shall be functionally suitable for garrison and field use under warm-wet climatic conditions with respect to comfort, foot and ankle support provided, ease of donning and doffing, adequacy of closure and drying characteristics, and protection afforded from underbrush, insects and other objects normally encountered when walking through the jungle.	Yes	See paragraph 2,2,4.
<ol> <li>The boots shall be durable when worn for extended periods under warm-wet climatic conditions.</li> </ol>	Partially	See paragraph 2.3.3.

# APPENDIX III, DEFICIENCIES AND SHORTCOMINGS

# 1. DEFICIENCIES

Remarks	NA		Remarks	Test participants were un- aware when cracks devel- oped. This fallure occurred on five boots.	This failure occurred on seven boots.	This failure occurred once during the test period.	This failure occurred in approximately 30% of the insoles.
Suggested Corrective Action	NA	2. SHORTCOMINGS	Suggested Corrective Action	Unknown	Improve adhesive and forr the entire tread surface around the heel.	Unknown	Unknown
<u>Deficiency</u>	None		Shortcoming	a. Cracks developed at the junction of the rear of the center clests and front of the steel shank.	<ul><li>b. The bonding of the heel to the leather upper separated.</li></ul>	c. The cloth adjacent to the edging tape at top of the gusset tore when participant was donning the boot.	d. The saran insole frayed on the edges and in the area of the ball and heel of the foot.

# APPENDIX IV. MAINTENANCE EVALUATION

Other than the normal polishing of the boot leather, the only maintenance required was cleaning the mud and rocks from between the cleats of the boot. This was accomplished with either a stick or small tool, and required only a minimal amount of time. Ease of maintenance would be enhanced by having the cloth portion of the boot colored black.

# APPENDIX V. PHOTOGRAPHS



Figure 1. Front and side view of Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield.




Figure 2. Rocks and mud lodged between cleats on heel and sole of test boot.




Figure 3. Bonding failure (separation of the heel from the upper).




Figure 4. Dislodged ventilation and drainage eyelet.




Figure 5. Frayed gusset top with edging tape pulled off.




Figure 6. Cracking at cleat-sole junction.

#### APPENDIX VI. REFERENCES

- 1. RDT&E Project No 1M643303D547.
- Letter, QMGRE-D, Office of the Quartermaster General, 17 October 1961, subject: Protection Against Foot Penetration Devices.
- 3. Report of USATECOM Project Nos. 8-3-6010-01K and 8-3-6010-02K, Integrated Engineering/Service Test of Boot, Combat, Tropical, DMS, with Sole Shield, Spike Resistant, US Army Infantry Board and US Army Quartermaster Research and Engineering-Field Evaluation Agency, January 1964.
- 4. Third Indorsement, AMCRD-DM-E (19 Sep 63), US Army Materiel Command, 7 July 1964, subject: Protection Against Foot Penetration Devices.
- 5. Letter, AMSTE-BC, US Army Test and Evaluation Command, 14 July 1964, subject: Test of Boot, Combat, Tropical, DMS with Sole Shield, Spike Resistant.
- Letter, AMSTE-BC, US Army Test and Evaluation Command,
   November 1964, subject: Test Directive, USATECOM Project
   No 8-5-6010-01, 8-5-6010-02, Engineering and Service Test of Spike Resistant Insole.
- 7. Letter, AMSTE-BC, US Army Test and Evaluation Command, 9 September 1965, subject: Final Report of Engineering Test and Service Test of Spike Resistant Insole.
- 8. Letter, AMXRE-COP, US Army Natick Laboratories, 7 October 1965, subject: Final Report of Engineering Test and Service Test of Spike Resistant Insole.
- 9. Discussion, Committee 8, USATECOM Desert/Tropic Test Planning Conference, 16 November 1965, subject: ET/ST of Boot, Combat, Tropical, DMS with Sole Shield, Spike Resistant.
- 10. Letter, AMSTE-BC, US Army Test and Evaluation Command, 26 November 1965, subject: Test Directive Engineering and Service Test of Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, USATECOM Project No 8-6-6010.
- Plan of Service Test of Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, US Army Tropic Test Center, December 1965.

# APPENDIX VII. DISTRIBUTION LIST

Distribution denoted by an asterisk (\*) will be made from those copies forwarded to Headquarters, US Army Test and Evaluation Command.

Agency	Test Plan	Interim Report	Final Report
Commanding General US Army Materiel Command ATTN: AMCRD-DM-E Washington, D. C. 20315	5*		5* 3*
Commanding General US Army Materiel Command ATTN: AMCQA Washington, D. C. 20315			1*
Commanding General US Army Natick Laboratories ATTN: Review & Analysis Div Natick, Massachusetts 01760	5	2	20
Commanding General US Army Combat Developments Command ATTN: CDC LO, USATECOM Aberdeen Proving Ground, Maryland 21005	10*	10*	10*
Commanding General US Army Test & Evaluation Command ATTN: AMSTE-BC Aberdeen Proving Ground, Maryland 21005	30	11	30
President US Army Infantry Board Fort Benning, Georgia 31905	1	1	1
President US Army Airborne, Electronics and Special Warfare Board Fort Bragg, North Carolina 28307	1	1	1
Commandant US Marine Corps Washington, D. C. 20315			1

Agency	Test Plan		_
Commanding Officer	1	1	1
US Army General Equipment Test Activity			
Fort Lee, Virginia 23801			
Commandant			1
US Army Infantry School			
ATTN: AJIIS-M			
Fort Benning, Georgia 31905			
Commanding General			4
US Continental Army Command			
ATTN: DCSIT-SCH-PD			
Fort Monroe, Virginia 23351			
Director	1	1	1
Marine Corps Landing Force			
Development Center			
Quantico, Virginia 22134			
Commander			20
Defense Documentation Center for Scientific & Technical Information			
ATTN: Document Service Center			
Cameron Station			
Alexandria, Virginia 22313			
cracemine and 1449 with meday			

Security Classification

DOCUMENT CO (Security classification of title, body of abetract and index	NTROL DATA - R&I		he overall report is classified)	
1 ORIGINATING ACTIVITY (Corporate author)		2ª REPOR	TT SECURITY C LASSIFICATION	
US Army Tropic Test Center			assified	
Fort Clayton, Canal Zone		entered when the overall report to classified)  2s REPORT SECURITY CLASSIFICATION  Unclassified  2b GROUP  NA  IKE RESISTANT SOLE SHIELD  PAGES  7b. NO OF REFS  11  REPORT NUMBER(5)  IT NO(5) (Any other numbers that may be assigned  der only with specific prior  ILITARY ACTIVITY  Itick Laboratories		
		NA		
SERVICE TEST OF BOOT, COMBAT, TROPICAL	., DMS WITH SPIK	e resis	TANT SOLE SHIELD	
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)				
Final Report February 1966 - June 1966	<u> </u>			
S. AUTHOR(S) (Last name, liret name, initial)  Sims, Columbus Jr., Master Sergeant				
6 REPORT DATE	78 TOTAL NO OF P.	AGES		
August 1966	33		11	
BB: CONTRACT OF BRANT NO.  RDT&E Project No 1M6433C3D547  B PROJECT NO.  USATECOM Project No 8-6-6010-01	Se ORIGINATORIS RE	EPORT NUM	BER(S)	
<b>c</b> .	9b. OTHER REPORT NO(S) (Any other numbers that may be assigned this report)			
d.	NA			
10. A VA IL ABILITY/LIMITATION NOTICES				
This document may be further distribut approval of US Army Natick Laboratorie		r only	with specific prior	
11. SUPPLEMENTARY NOTES	12. SPONSORING MILE	TARY ACT	VITY	
None	US Army Natick Laboratories Natick, Massachusetts 01760			

13 ABSTRACT

The Boot, Combat, Tropical, Direct Molded Sole with Spike Resistant Sole Shield, was service tested by the US Army Tropic Test Center in the Canal Zone during the period 21 February thru 21 June 1966. The test sample consisted of 85 pairs of boots. The boots were worn by personnel from airborne, mechanized, and regular infantry battalions, special forces units, and by field cadre at the US Army School of the Americas and the US Air Force Tropic Survival School. Use included local unit training and field exercises. (Test of protection against spikes was conducted by the US Army General Equipment Test Activity at Fort Lee, Virginia, and was not a part of the tropic test.) The test boot was found to be functionally suitable for field and garrison wear in the warm wet climate. The bonding of the rubber sole and heel and the ventilation and drainage eyelets are satisfactory to withstand at least 121 days use under rugged field conditions. Cracks developed in the center cleat-sole junction of the rubber sole on five pairs of boots during normal use. Seven failures were noted in the bonding of the rubber heel to the outsole. It was recommended that the Boot, Combat, Tropical, DMS with Spike Resistant Sole Shield, be considered suitable for Army use when shortcomings are corrected.

12-2246

DD 15084 1473

Unclassified

Security Classification

LINK A		LINK B		LINK C	
ROLE	wŦ	HOLE	wT	ROLE	*

- 1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of Defense activity or other organization (corporate author) issuing the report.
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.
- 2b GROUP: Automatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as authorized.
- 3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis immediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.
- 5. AUTHOR(3): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an absolute minimum requirement.
- 6. REPORT DATE: Enter the date of the report as day, month, year, or month, year. If more than one date appears on the report, use date of publication.
- 7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.
- 7b. NUMBER OF REFERENCES: Enter the total number of references cited in the report.
- 8a. CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.
- 8b, 8c, & 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.
- 9a. ORIGINATOR'S REPORT NUMBER(S): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.
- 9b. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).

- 10. AVAILABILITY/LIMITATION NOTITES: Enter any limitations on further dissemination of the report, other than those imposed by security classification, using standard statements such as:
  - "Qualified requesters may obtain copies or this report from DDC."
  - (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
  - (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
  - (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through
  - (5) "All distribution of this report in controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known.

- 11. SUPPLEMENTARY NOTES: Use for additional explanatory notes.
- 12. SPONSORING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.
- 13. ABSTRACT: Enter an abstract giving a brief and factual summary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical report. If additional space is required, a continuation sheet shall be attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS), (S), (C), or (U).

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KFY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no security classification is required. Idenfiers, such as equipment model designation, trade name, military project code name, geographic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, rules, and weights is optional